
## Property Boundary Survey

A tract of land in US Survey 1012 T47N, R7E St Louis County, Missouri



Lot 95

Country Village Hills III

Plat Book 223 Page 40

G

 $\bigcirc$ 

Fox Woods Plat One

100

SCALE: 1 inch = 50 ft.

BASIS OF BEARINGS:

Assumed

Legend

Found Rebar

O Found Iron Pipe

Set Rebar

Found Stone

(f) Found RR Spike/CPS

Found Right of Way Marker

Project 1005NG05excess

## Certification

or less.

Property Description

Missouri and being more particularly described as:

recorded in Book 192 Page 8, St Louis County Recorders Office; thence, N36'01'34"E, 195.18'; thence, S88'29'41"E, 138.86'; thence,

177.75': thence, N80'31'08"W, 145.26'; thence along a curve to the left. radius 175.00', length 193.61', chord N22'14'45"W. 184.05' to the

This is certify that at the request of Missouri Highways and Transportation Commission, I performed a boundary survey in part of a tract of land in US Survey 1012, T47N, R7E, St Louis County, Missouri. The results of said survey are shown hereon and meet or exceed the Minimum Standards for Suburban Property Boundary Surveys as established by the Missouri Board For Architects, Professional Engineers, Professional Land Surveyors and Landscape Architects.

## Disclaimer

This survey is made subject to easements, Rights of Way and prescriptive rights whether of record or not to include any recorded or valid existing restrictions, reservations, covenants, conditions, severances and other instruments that may affect subject property.

This surveyor does not certify to the existence or non-existence of any underground utilities that may or may not exist within the boundaries as shown. Only those utilities that were visible at the time of survey are shown.

This survey was performed without the benefit of a title commitment.